

Novatac EDC-85P or 120P

Usage Flowchart

CPF Member – bluecrow76
Version 0.2



Soft Reset

Turn the light on.
Unscrew the battery case until the light turns off.
Screw the battery case back together; there will be one second of dim light.
The soft reset is complete.

Battery Detect Reset

Turn the light on.
Unscrew the battery case until the light turns off.
Screw the battery case back together; there will be one second of dim light.
During the one second of dim light, press and hold the button.
You will see five seconds of bright light, followed by dim light.
Release the button when the light goes dim.
The battery detect reset is complete.

Factory Reset

Turn the light on.
Unscrew the battery case until the light turns off.
Screw the battery case back together; there will be one second of dim light.
During the one second of dim light, press and hold the button.
You will see five seconds of bright light, 3 seconds of dim light, 2 seconds of bright light then the light will go out.
Release the button when the light goes out.
The factory reset is complete.

